OK

Depth 6	Contents 7	Reference to last Measure 8

BR261/31-7-13

ASNO : 548/12-13 dt 30-7-2013

T.SNO : 337/12-13 dt 31-7-2013

M. A. R. 57 (Rule 116) **No. B**

Measurement Book

Job Call : 014-13-00001/82622

Issue 19.306

SBR56/31-7-13

Name of work ... Improvement to drainage at Bagalagunte main road Right side in ward no-14 by plower

Name of Agency ... M. Ratnakar No 9, 34th Cross Jungamaheshwarapalya

Amount of work ... Ratati wages

(Ward No. 14) Dimensions 26/12-14 dt 17.8.2013

Description, etc, of work 2	Number 3	Length 4	Breadth 5	Depth 6	Contents 7	Reference to last Measurement 8
...ding Sweeping Structure Line Culvert Bridges. Rotary Wall and other ... Compressor of masonry Cement Concrete and Wire Stay Wire ... TCP and Staffolding where necessary Sinking the old Manhole ... disposal of unserviceable materials and Stacking the serviceable ... materials at site and lead of 100 metre Complete as per Specifications ... dismantling Stone masonry B. Rubble Stone masonry in Cement Mortar ... including premeasurement received vide PWO 82682 of this MB.			170 Mtrs		89.28	15177/-
... work Excavation for foundation of Bridge Water Supply Sanitary						